

## Handy Little Lathe Chart - Spindle Speeds by Chart Version

STOCK NUMBER	MAKE / SIZE	SPINDLE SPEEDS							
HLLC-U14	Slow Universal	25	50	100	200	300	400	500	600
		700	800	900	1000	1100	1200	1300	1400
HLLC-U30	Fast Universal	25	50	100	200	300	400	500	750
		1000	1250	1500	1750	2000	2250	2500	3000
HLLC-SU	Small Universal	50	75	100	150	200	250	300	400
		500	750	1000	1250	1500	1750	2000	2500
		3000	3500	4000	4500	5000			
HLLC-A10	Atlas 10"/12"	28	45	70	112	83	134	211	345
		164	266	418	685	500	805	1270	2072
HLLC-A6	Atlas 6"	55	82	125	185	145	210	315	463
		380	540	835	1185	975	1380	2150	3050
HLLC-L9/10	Logan 9" / 10"	55	80	112	144	200	253		
<i>(Special Order Chart)</i>		353	459	645	831	1157	1450		
HLLC-L9/10e	Logan 9" / 10" Early	30	56	70	104	131	244		
<i>(Special Order Chart)</i>		179	334	420	620	780	1450		
HLLC-L10/11	Logan 10" / 11"	38	53	69	96	82	112	148	205
<i>(Special Order Chart)</i>		228	318	414	490	576	676	888	1230
HLLC-CL10	Clausing 10"	52	62	75	125	174	237		
<i>(Special Order Chart)</i>		370	450	540	900	1250	1700		
HLLC-ACL12	Atlas-Clausing 12"	35	65	100	160	270			
<i>(Special Order Chart)</i>		210	375	650	995	1600			
HLLC-S3-5	Sherline 3.5"	70	252	434	616	798	980	1162	1344
<i>(Special Order Chart)</i>		1526	1708	1890	2072	2254	2436	2618	2800
HLLC-M7	7" Mini Lathe	138	275	413	550	688	825	963	1100
<i>(Special Order Chart)</i>		313	625	938	1250	1563	1875	2188	2500